

## Design of Experiment (DoE) Primer for Resistance Welding By David Steinmeier

The words, “Design of Experiment” generate instant fear in the minds of most manufacturing personnel responsible for any type of welding or joining process. Complex mathematics and software put off most people from even trying. This primer seeks to take the fear out of the DoE process and provide a starting point for conducting your own DoE on your next welding project.

### DoE Definition

The DoE process is simply a scientific approach to understanding how the input affects the output. Inputs include some combination of machines, materials, methods, people, and environment. Outputs include quantitative measurements like pull testing and subjective factors like electrode sticking.

### Why Use the DoE Process?

The DoE process is the quickest way to identify which input variables are important, how the key input variables relate to output measurements, and where on the set of operating curves do you need to be to have a robust welding process. Six-sigma manufacturers are insisting on reducing scrap and to do that, they must have a robust welding process.

### What Are the Limitation of the DoE Process?

The DoE process can not replace a thorough understanding of any process, nor can it find “missing input variables” or provide a starting point to begin DoE experiments. These “negatives” are far outweighed by the positive reasons for using a DoE and this primer will provide you with a starting point strategy.

### Step 1 – Identify Key Input Variables

Identify both the controllable and un-controllable input factors. The Table A lists some of the key input variables for making a resistance weld with two different materials.

### Step 2 – Reduce Input Variables

Reduce the number of controllable input variables to no more than four. Fix variables like electrode tip area, tip material, and Overlap. Your selection of material for parts A and B automatically places controls on the material alloys and plating. Guard against possible inadvertent changes that can occur due to plating thickness variations in a new lot run of material.

**Table A – Key Resistance Welding Variables**

Variables	Controllable	Un-Controllable
Weld Power	Y	
Weld Time	Y	
Weld Force	Y	
Electrode Tip Area	Y	
Electrode Tip Material	Y	
Electrode/ Material Position *1	Y	Y
Electrode Gap	Y	
Material [A]	Y	
Material [A] Plating Thickness *2		Y
Material [B]	Y	
Material [B] Plating Thickness *2		Y
Material Overlap *1	Y	Y

\*1 Controlled by automated assembly. Not controlled by hand assembly.

\*2 Vendor controlled within specified tolerance.

### Step 3 – Identify Key Output Measurements

Identify key output measurements. Table B shows some typical resistance welding output measurements.

**Table B – Output Measurements**

Output Measurement	Quantifiable	Un-Quantifiable
90° Peel	Y	
180° Pull	Y	
Electrode Sticking		+1 = None 0 = Slight -1 = Severe

### Step 4 – Find The “Corners of The Box”

The software that generates the DoE procedure does not provide the minimum and maximum input factor values. The experimenter must generate these values before beginning the DoE.

# microJoining Solutions – microTips™

5563 Hallowell Avenue • Arcadia, CA 91007

Phone: 626-444-9606 • Fax: 626-279-7450 • Email: mjs@microjoining.com • Web: www.microjoining.com

To find the minimum “corner of the box”, experiment with weld energy, time, and force to produce a weld that just sticks together when pulled. Hold all other input variables constant.

To find the maximum “corner of the box”, experiment with the same variables to produce a strong weld with minimum electrode sticking.

Use the *minimum* force value and *maximum* energy and time values to make a weld. Does it blow up? If so, reduce the weld energy until minimum electrode sticking is achieved. Use your final min and max values in the DoE set up procedure.

## Step 5 – Conduct the DoE

To conduct the following DoE procedure, you will need to obtain a copy of the *Kiss®* DoE software from Digital Computations and Air Academy Associates (719-531-0777). This author uses *Kiss DoE Pro®*.

Using the *Kiss* software, set up a 3-Level, 3 or 4 factor (input variable) L9 Taguchi experiment. Use at least 5 repetitions at each weld setting to get the average pull strength. There are 9 different weld settings for the L9 Taguchi DoE.

## Step 6 – Analyze the DoE

After completing the DoE, you must run the regression model. This action creates a prediction model relating the inputs to the outputs. Don’t worry about understanding the regression model. The model provides access to the plotting function, which allows you to plot each input variable combination against the output measurement.

The following plots represent an opposed weld consisting of two pieces of tin plated kovar ribbon.

- First Plot = Power versus Weld Time
- Second Plot = Power versus Weld Force
- Third Plot = Power versus Material Overlap

## Step 7 – Select the Optimum Weld Settings

The most robust welding process occurs using the following combination:

Power (KW)	Time (msec)	Force (lbs)	Overlap (inches)
1.185	26.5	11.5	0.3

