

Table of Contents

Chapter 1

Design of Experiment Process	1
Introduction.....	2
Basic Approach.....	2
Design of Experiment Definition.....	2
Why Use the Design of Experiment Process?	3
Design of Experiment Limitations	3

Chapter 2

Getting Started - Identify the Key Input Factors	4
Input Factor Universe	5
Power Supply Parameters	5
Weld Head Parameters.....	6
Electrode Parameters.....	6
Material Parameters	7
Material Geometry Factors	8

Chapter 3

Reduce the Number of Input Variables	9
Life is Too Complex	10
The Reduction Process.....	10
Opposed Weld Example.....	11
Parallel Gap Example.....	12

Chapter 4

Identify the Key Output Responses	13
Output Response Universe.....	14
Weld Quality Definition.....	14
Quantifiable Output Response Measurements	15
Qualitative Output Responses.....	15

Chapter 5

Find the “Corners of the Box”	16
Resistance Welding Box.....	17
“Move the Box”	17
DoE Software Capability	17
Find the Minimum “Corner” – Opposed Weld Example.....	18
Find the Maximum “Corner” – Opposed Weld Example.....	19
Find the Minimum “Corner” – Parallel Gap Weld Example	19
Find the Maximum “Corner” – Parallel Gap Weld Example	20
Test the “Corners”	21

Chapter 6

Conduct the DoE	22
DoE Software Selection.....	23
Opposed Weld Example.....	23
Parallel Gap Weld Example.....	25

Chapter 7	
Analyze the DoE	27
General Analysis Approach	28
Prediction Models	28
“Rules of Thumb”	29
Adjusted Coefficient of Determination (Adj Rsq)	29
P(2 Tail)	29
Coeff.	29
Opposed Weld Example	30
Run the Multiple Regression	30
Check Y-hat and S-hat Model Validity	30
Revise the S-hat Model	31
Optimize the Prediction Model	32
Plot the Output Response	35
Perform the Confirmation Run	38
Analyze the Confirmation Run	38
Parallel Gap Weld Example	39
Run the Multiple Regression	39
Check Y-hat and S-hat Model Validity	39
Revise the S-hat Model	40
Optimize the Prediction Model	41
Plot the Output Response	42
Perform the Confirmation Run	46
Analyze the Confirmation Run	46
Summary	47
Glossary	48
Index	50